Los Altos Hills Maintenance June 2016

Task	Monthly Summary	Unit Cost	Quantity	12-Month Cost	Actual Unit Per Month		Year to Date Cost	Year to Date Quantity	Quantity Remaining	Remaining Budget
Bid Item No. 1. Pump Station Maintenance	PURISSIMA Station: The weekly inspections, ATS and Generator testing were performed. No Unscheduled repairs were perfomed. Replace the stationary wear ring in dry pit pump number 2. O'Keefe Court Station: The weekly inspections, ATS and Generator testing were performed. Items to be addressed: Guide Rails should be changed out to Stainless Steel per industry standard and for reliable use from the current rusted galvanized rails. Replace Pump Number 2's lifting handle. (See Tab 1.)	\$1,720	12	\$20,640.00	1	\$1,720.00	\$18,920.00	11	1	\$1,720.00
Bid Item No. 2. Cleaning and Flushing in Right of Way	Work Performed: Cleaned 4,319 feet of pipe within the public right-of-way. Results were noted in the CMMS. Recommendation: Continue to clean ahead	\$1.05	99,000	\$103,950.00	4,319 4,358	\$4,534.95	\$84,226.80	80,216	18,784	\$19,723.20
Bid Item No. 3. Cleaning and Flushing in Easements	Work Performed: Cleaned 5,590 feet of pipelines in easements. Results were noted in the CMMS. Recommendation: Continue to clean ahead of the CCTV unit. (See Tab 3.)	\$1.45	36,000	\$52,200.00	5,590	\$8,105.50	\$72,411.55	49,939	(13,939)	(\$20,211.55)
Bid Item No. 4. CCTV Inspection within Right of Way	Work Performed: CCTV inspected 2,173 feet of pipelines that are Right of Way. NASSCO PACP standards were used and Structural and O&M condition ratings and defect codes were used and entered into the CMMS system. Recommendation: Perform 7 Pipe Patches and 1 Open Trench Repairs. In addition, monitor one minor break in MH EMH1191 to EMH1192 and Recommend Replacing a 6 inch "Drop" to an 8 inch drop to match the mainline. (See Tab 4.)	\$1.44	68,000	\$97,920.00	2,173 2,171	\$3,129.12	\$74,433.60	51,690	16,310	\$23,486.40
Bid Item No. 5. CCTV Inspection within Easements	Work Performed: CCTV inspected 5,148 feet of pipelines in easements. NASSCO PACP standards were used and Structural and O&M condition ratings and defect codes were used and entered into the CMMS system. Recommendation: Perform 2 Pipe Patch Repairs and consider replacing a line segment that transitions from 6 inch to a 4 inch sewer main. In addition, monitor a minor break in ECO1018 to EMH1178 (See Tab 5.)	\$1.85	25,000	\$46,250.00	0-K5,148-	\$9,523.80	\$67,784.00	36,640	(11,640)	(\$21,534.00)
Bid Item No. 6. Response to SSOs with access from Right of Way	West Bay did not respond to Sanitary Sewer Overflows for the Town this month within right of way.	\$1,500	6	\$9,000.00	-	\$0.00	\$6,000.00	4	2	\$3,000.00
Bid Item No. 7. Response to SSOs with access from Easements only	West Bay did not respond to Sanitary Sewer Overflows for the Town this month within an easement.	\$1,680	6	\$10,080.00	-	\$0.00	\$1,680.00	1	5	\$8,400.00
Bid Item No. 8. GIS Mapping Maintenance and Updates (By the Hour)	Updated GIS Mapping and Maintenance Data Updates.	\$129	120	\$15,480.00	3	\$387.00	\$6,450.00	50	70	\$9,030.00
Bid Item No. 9. Monthly Management Reports	Developed the monthly summary report and follow up work for the Town.	\$361	. 12	\$4,332.00	1	\$361.00	\$3,971.00	11	1	\$361.00
Bid Item No. 10. Sanitary Sewer Overflow Response for Private Laterals	West Bay will respond to SSOs related to private laterals, including determining ownership, notifying the owner of the issue, providing the owner with the Town's Sewer Spill Reference Plan, and entering information into the CMMS system.	\$319		\$1,914.00		\$0.00		1	5	\$1,595.00
Control of the second	(1) · · · · · · · · · · · · · · · · · · ·	- Call 235	Total	\$361,766.00	0	\$27,761.37	\$336,195.95	5		\$25,570.05

\$ 27,799.44